



# CARTA DE TEMPERATURAS

## ESCUELA DE HERREROS



Toledo

La carta de temperaturas debe observarse con luz natural en sombra.

### Colores de REVENIDO

El acero debe estar pulido y observarse con luz natural buscando los reflejos.

### Colores de FORJADO y TEMPLE

El acero debe observarse en penumbra.

°C	10 min.	30 min.		
380			2462°F	1350°C
360			2372	1300
340			2282	1250
320			2192	1200
300			2102	1150
290			2012	1100
280			1922	1050
270			1832	1000
260			1742	950
250			1652	900
240			1562	850
230			1472	800
220			1382	750
210			1292	700
			1202	650
			1112	600